





Field Guide


F3 Compact Mine Detector






Unfolding Procedure





Pack Up







1. Switch On



2. Ground Balance







3. Test Piece



4. Audio Reset






5. Noise Cancel



Hold for 2 seconds



Volume Control



Default Setting

